

Safety/Security Alert #2007-01b

(issued 04/19/2007)

ELECTRIC JUNCTION BOX (HAND-HOLE) MALFUNCTION – UPDATE #2

This message updates Advisory #2007-01, originally issued on 3/22/07, which informed BSL residents of an electric service incident, namely an explosion and fire in a junction box, or "hand-hole," on Isaac Lane. In a subsequent Update on 4/02/2007, residents were informed that FPL had agreed to conduct inspections of all hand-holes in Burnt Store Lakes in the "near future."

Today, the POA received word from FPL that hand-hole inspections will begin within the next week. BSL residents can expect to see employees from Pike Electric, a FPL subcontractor, working throughout the community inspecting each hand-hole. These inspections should cause no disruption of electric service unless, of course, problems are found and repairs are needed.

Note: In order to conduct an inspection, workers may need to trim back or remove any plantings that hinder access to the hand-hole. Residents may wish to inspect existing plantings near the hand-hole and perform landscaping steps before arrival of the work crews.

Please contact the POA Office at 639-5881 if there are any questions.

BSLPOA Board of Directors
Safety and Security