



**Safety/Security Advisory #2007-01d
(Issued 07/20/2007)**

ELECTRIC JUNCTION BOX (HANDHOLE) MALFUNCTION – UPDATE #4

This message is the 4th and final update to Advisory #2007-01, concerning the electric service malfunction of a junction box, or "handhole," in Burnt Store Lakes on March 20, 2007.

Florida Power and Light has provided the BSLPOA with a summary of their inspection of handholes in the community. Between April 23 and May 21, an FPL approved sub-contractor inspected all 365 handholes within Burnt Store Lakes. These inspections centered on three specific problems: 1) signs of corrosion, 2) damage to cable or connections, and 3) loose connections. During these inspections, electric service at the meter was also checked to insure a safe connection.

FPL's inspections found that 10% of the handholes contained one or more of the above noted problems. As a result, connections in each of those handholds were replaced. In addition, FPL reported making other, associated repairs, such as replacing water barriers, and re-aligning handholes to grade level.

While BSL residents and homeowners can be confident that electric service is being provided in a safe manner, we should all remain alert to any noticeable change in service, such as rapidly flickering lights, and promptly contact FPL's service hotline at 1-800-4OUTAGE (1-800-468-8243).

Internet communications are not assured to be secure or clear of inaccuracies as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore, we do not accept responsibility for any errors or omissions that are present in this e-mail, or any attachment, that have arisen as a result of e-mail transmission.